

In the specification:

Page 5, after line 2, insert:

-- Figure 6 is a view showing planes in which two perpendicular axes of cross of the cardan joint are located. --

Page 7, after line 2, insert:

-- Plane 16 extends through an axis of rotation of the axis 2 and the axis 15 of the rod 5. Plane 17 is perpendicular to the axis 16 and extends through the axis 15. Axes 6 and 7 are perpendicular to the axis 15 and are located in the planes 17 and 16. --

REMARKS

The last Office Action has been carefully considered.

It is noted that claims 3 and 4 are rejected under 35 U.S.C.

112.